






E: Big River
 MDP 9211-1877
 Date: 1/7/88
 By: [Signature]
 4-88



EXPLANATION

-  FILLED GAP
-  EXISTING GAP
-  DRAINAGE STRUCTURE
-  ACCESS ROAD

SCALE



**BIG RIVER MINE TAILINGS
DESLOGE MISSOURI**

WASTE SITE TRACKING # MO0616
 PREPARED BY R OVERFELT

ECOLOGY & ENVIRONMENT APRIL 1988
 SOURCE REFERENCE 4

40111745



SUPERFUND RECORDS

FIGURE 3 MAJOR EROSIONAL FEATURES

Fm0666PA
 08-4